

Project Purpose

Routine maintenance that includes numerous aesthetic repairs to the spillway at Lake Lenexa.

Project Description

Repairs will be made to the spalling concrete veneer on the spillway itself, some of the decorative concrete in the lower spillway steps, and at the railings along the top of the spillway wall.

Location

Blackhoof Park at 91st Street & Monticello Road

Designer

Olsson Associates

Contractor

Golconda

Construction Timeline

Start Date: October 2012

Estimated Completion Date: Fall 2013




Total Cost

\$75,000

Funding Sources

City: 100%

- Stormwater cash



City of Lenexa

12350 W. 87th Street Parkway
Lenexa, Kansas 66215
www.lenexa.com

Project Manager

Tom Jacobs, Stormwater Engineer
tjacobs@lenexa.com
913.477.7644

Project Inspector

Mike Shipman, Construction Inspector III
mshipman@lenexa.com
816.830.0006